Environmental redundancy lost

Published 04/11/2001

Symptom(s):

ESP Class Description: System Controller
Environmental redundancy lost
Syslog Message: WARNING: 001i14 ATTN: Environmental redundancy lost
ESP Type Description: Environmental redundancy lost
ESP Event Type Id: 177

Fact(s):

SGI Origin 3000
IRIX 6.5.X

SGI Solution:

This warning indicates a cooling fan has failed.

The system controller display indicates which fan has failed.

This failure is not critical as there are redundant fans. However, fan redundancy is now lost and further failures will result a system down. A replacement fan should be ordered and installed as soon as convenient. Contact your support center for further information.

Reference: part number 013-2800-001

Cause(s):

Fan failed and needs to be replaced

Additional Details

Creation Date	02/20/2001 10:12 AM
Last modification	10/01/2015 02:21 AM
Published Date	04/11/2001
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution